OK-5129H

ASSEMBLY INSTRUCTION

1.INDOOR USE ONLY
2.REPLACE THE BULB AFTER THE BULB GETS COOL







Assembly steps:

Step 1. Hang crystal strand(①)in hole(A4).

Step 2. Screw screw(E) through nut(D)、glass(C)and metal plate(A2). Secure with nut(F).

Step 3. Screw bulb(M) into socket(A3).

Step 4. Mount shade(B) on threaded bolt(A1)and secure with finial loop(G).

Step 5. Screw loop(G) into tube(I).

Step 6. Loosen screw(J) and pass canopy (K) over tube(I).

Step 7. Screw loop(L) into tube(I).

Step 8. Pass the main wire through loop(G), canopy(K), tube(I) and loop(L).

Step 9. Attach each end link(H)of chain to finial loops(G) and (G).

step 10. Connect wire to the power supply cord.

Step 11. Raise canopy(K)to ceiling and secure by tightening screw(J).

Step 12. Hang loop(L)onto hook on ceiling.

After completed above instructions, please check once over to ensure safety. Then you may turn power on. If external cable or cord is damaged, it should be replaced by a qualified person to avoid hazard.